

LDWSEF
4.8.1
2/18/14

Sanga, Ravi


From: Dyer, Miles [mdyer@JorgensenForge.com]
Sent: Tuesday, February 18, 2014 12:07 PM
To: Sanga, Ravi
Cc: Ernst, William D
Subject: FW: Response to Ravi's ltr dtd2-13-2014
Attachments: EPA Ltr 2 15 2014 JFC - Site Location - Figure 1 - 20140110.pdf; EPA Ltr 2 15 2014 JFC - Property Features - Figure 2 - 20140110.pdf; 2014-02-12-13092-S1_1-OPT 1.pdf; EPA Ltr 2 15 2014 JFC - Previous Clean-up Efforts - Figure 3 - 20140110.pdf; Joint Signed Response to EPAs ltr dtd 13 Feb 2014.pdf

Ravi,

As discussed earlier today, I have attached drawing (2014-02-12-13092-S1_1-OPT1) which provides the graphic showing the position of the coffer dam in relationship to JFC and Boeing's property. Request EPA consider this additional drawing an acceptable graphic instead of modifying Drawing # 3 per EPA's letter dated 13 February 2014.

Thank you for your assistance

Miles Dyer
Director, Environmental Programs



Jorgensen Forge Corporation
8531 East Marginal Way South
Seattle, Washington 98108
Office Ph#: (206) 965-1352
Mobile: (740) 777-7808
Fax: (206) 357-1071
mdyer@jorgensenforge.com

***** ATTACHMENT NOT DELIVERED *****

This Email message contained an attachment named
image001.jpg

which may be a computer program. This attached computer program could contain a computer virus which could cause harm to EPA's computers, network, and data. The attachment has been deleted.

This was done to limit the distribution of computer viruses introduced into the EPA network. EPA is deleting all computer program attachments sent from the Internet into the agency via Email.

If the message sender is known and the attachment was legitimate, you should contact the sender and request that they rename the file name extension and resend the Email with the renamed attachment. After receiving the revised Email, containing the renamed attachment, you can



rename the file extension to its correct name.

For further information, please contact the EPA Call Center at
(866) 411-4EPA (4372). The TDD number is (866) 489-4900.

***** ATTACHMENT NOT DELIVERED *****



NOTE:

1. AERIAL IMAGERY PROVIDED BY THE UNITED STATES GEOLOGICAL SURVEY COLLECTED IN 2013 AS PART OF THE NATIONAL AGRICULTURE IMAGERY PROGRAM.




FIGURE 1

**JORGENSEN FORGE
PROPERTY LOCATION**

JORGENSEN FORGE CORPORATION/THE BOEING COMPANY
JORGENSEN FORGE OUTFALL SITE

LEGE



NOTES:

1. AERIAL
GEOL
2. BOUNDARY
AREAS
STRATIGRAPHY
BORING
3. PROPERTY
GIS; IS

